

Majestic Granite Polishing Powder



A natural abrasive powder to restore your polished granite to its like-new shine. This powder is ideal for the final step in the restoration process or ongoing maintenance. Available for both light and dark colored granite to keep your floors looking their best.

For Use On: All granite surfaces.

Available Sizes: 1 lb., 2 lbs., 5 lbs., 10 lbs., 25 lbs.

Coverage: 150 ft./lb.

Product Features:

- Excellent for renewing all types of granite
- Removes light scratches
- Easy to use formula

THOROUGHLY TESTED

Directions:

- Light:**
1. Protect all adjacent surfaces with masking film or plastic. Remove all waxes and finishes using Majestic Deep Cleaning Stripper Degreaser.
 2. Sprinkle one scoop (four tablespoons) Polishing Powder on the floor to cover an area about the size of the buffing pad. Plan to polish a 3 ft. x 3 ft. section of the floor at a time.
 3. Spray Polishing Powder with 10-12 squirts of water.
 4. Place the buffing pad and machine over the mix and begin buffing the area - moving the machine constantly.
 5. Buff the area until the slurry is almost dry. Add more water and buff out again. Repeat this step several times.
 6. If the desired shine is not achieved, add more Polishing Powder and repeat Step 4.
 7. Mop the area with Majestic No-Rinse Neutral Cleaner.

- Dark:**
1. Protect all adjacent surfaces with masking film or plastic. Remove all waxes and finishes using Majestic Deep Cleaning Stripper Degreaser.
 2. Sprinkle one scoop (four tablespoons) Polishing Powder on the floor to cover an area about the size of the grade #0 steel wool pad. Plan to polish a 3 ft. x 3 ft. section of the floor at a time.
 3. Spray Powder with 10-12 squirts of Majestic Spray Polish Crystallizer.
 4. Place the steel wool pad and machine over the mix and begin buffing the area - moving the machine constantly. Buff the area until the slurry is dry. (May see a hazy film at this time)
 5. Change to a clean grade #1 steel wool pad, add 3-4 squirts of Polish only (no Powder) and buff again. To remove any remaining film, buff again with dry side of #1 steel wool pad.
 6. Repeat until you have achieved your desired shine.
 7. Mop the area with Majestic No-Rinse Neutral Cleaner.

M3 Technologies, Inc.
57 Lamberts Lane
Cohasset, MA 02025
Toll Free: 800-342-4533
Fax: 781-383-3135
www.m3techinc.com

